

#171 Cleaning Needed

Status

Open

Type

Issue

Location

1718 Corridor

Description


Clean wall base next to mail room door

Photos



Sheet

A-410.00



#170 Cleaning Needed

Status

Open

Type

Issue

Location


1710 PO-B

Description

Cleaning Needed

Sheet

A-410.00



#169 Acoustical Ceiling

Status

Open

Type

Issue

Location


1718 Corridor

Description

Re-seat ceiling tile with sprinkler head

Sheet

A-410.00



Photos



#167 Door

Status

Open

Type

Issue

Location


1713 Small Conference Room

Description

Door top hinge needs adjustment. Squeaks when opened.

Sheet

A-410.00



Photos



#164 Audio/Visual

Status

Open

Type

Issue

Location

1705 Large Conference Room

List

Punch List

Description


Adjust microphones to be flush with acoustic baffles.

Photos



Sheet

A-410.00



#163 Ceiling

Status

Open

Type

Issue

Location

1705 Large Conference Room

List


Punch List

Description

Patch and repair holes at baffle cable connection locations, typ.

Sheet

A-510.00



Photos

